




G1	G2	E max.	Ø	SW1	SW2	L1	L2	L3
M5	G 1/8"	8,0	10,0	14	14	15	12	4
G 1/8"	G 1/4"	10,0	14,0	17	17	18	14	4
G 1/4"	G 3/8"	14,0	17,0	22*	22	22	18**	4***
G 3/8"	G 1/2"	16,0	21,5	24	27	26	21	5
G 1/2"	M28 x 1,5	20,0	28,5	32	36	33	27	7
G 3/4"	M34 x 2	24,0	34,5	41	41	36	30	6
G 1"	M42 x 2	26,0	42,5	46	50	42	34	8
G 1 1/4"	M49 x 2	29,5	49,5	55	55	47	39	9,5
G 1 1/2"	M54 x 2	29,0	54,5	60	60	47	39	10